

PRODUCT DATA SHEET

AUTOSYN 6

(AUTOMATIC TRANSMISSION FLUID)

DESCRIPTION

Prolube Autosyn 6 is an Automatic Transmission Fluid formulated from Synthetic base oils blended with a new generation additive package to provide a highly shear-stable automatic transmission fluid which meets the specific requirements of an extensive range of American, European and Asian vehicles and meeting Ford Mercon® V.

It extends transmission life via performance anti-wear additives, enhanced frictional properties for smoother gear changes, reduced deposit formations, longer service life due to the full synthetic base stocks and shear-stable additive technology.

Viscosity - Typical 7.3 cSt @ 100°C

APPLICATION

A multi-vehicle ATF for use in the latest model American, European and Asian vehicles. Suitable for most North American models, Alfa Romeo, Fiat, Opel, & Scion vehicles plus others as per the list of recommended applications.

Not recommended for Ford Type F/G, DCT and CVT applications

STANDARDS

Meets the performance requirements of:

Ford MERCON-V®

JASO 1A

Allison C3, C4

Toyota T-III, T-IV

Hyundai/Kia SP-II, SP-III

MB 236.6

MAN 339 V-2, 339 Z-2, 339 Z-3 (Synthetic)

Volvo 97341

ZF TE-ML 04D, TE-ML 14B, TE-ML 14C (Synthetic),

TE-ML 16L, TE-ML 16M (Synthetic)

TE-ML 20B, TE-ML 20C (Synthetic)

CONTAINER SIZES

205 Litres, 60 Litres, 20 Litres, 5 Litres

Issue Date 1/11/2021



Lidomont Pty Ltd Trading as **Prolube Lubricants**
15 Pinnacle Street Brendale QLD 4500 | Ph: 07 3881 1733
sales@prolube.com.au | www.prolube.com.au
ABN: 64 010 867 428

Autosyn 6 is recommended for use for the following applications:

AE (LT71141 – ZF 5 Speed)
Alfa Romeo (all vehicles)
Aisin Warner JWS 3309, M315 A-1, T IV
Allison C-3, C-4
Allison TES 295 Allison TES 389 Allison TES 668
American Motors ATF +3 (SM7176-E, ATF+4 (MS9602)
AS 68 RC (T IV)
ATF Type A Suffix A
Audi/VW G-052-025-A2
Audi/VW G-052-162-A1
Audi/VW G-055-025-A2 (JWS 3309)
Audi/VW G-052-990-A2, G-055-540-A2
Audi 5 HP LT 71141 (ZF 5 HP 18 FL, 19FL, 24A)
Audi 5 HP LT 71141 (G-052-162-A1, A2)
Audi 5 HP (ZF 5 HP 30)
Bentley PY112995PA
BMW ETL-7045, 7045E (83 22 0 026 922)
BMW 7045E (3 series)
BMW LA2634
BMW 5 HP LT 71141 (ZF 5 HP 18 FL, 19FL, 24A)
BMW 5 HP LT 71141 (83 22 9 407 807)
BMW 5 HP (ZF 5 HP 30)
BMW ETL-8072B (83 22 0 024 359)
BMW 5 Series (Texaco ETL-8072B)
BMW MINI 83-22-0-402 413 9 (JWS 3309)
BMW 83-22-0-397114, 403249
BMW 83-22-2-163514
BMW 83-22-9-400272, 400275, 407765, 407858, 407 859
Caterpillar Power Shift TO-2
Chrysler ATF +3 (MS 7176-E)/+4 (MS 9602)
Chrysler Dodge MOPAR AS 68 RC (T IV)
Daimler NAG-1
Deawoo LT 71141
Daihatsu Alumix Multi
DSIH 6P805
Esso LT 71141
Fiat (All vehicles), TYPE T IV
Ford/Mazda V (XT-9-QMM5, FNR 5
Ford MERCON® (XT-2-QDR, XT-2-QSM SYN), ESR-M2C-163-A2
Ford MERCON® V
Ford MERCON® SP
Ford WSS M2C 922 A1, 924-A (XT-8-QAW) (JWS 3309)
GM DEXRON® II, IID, IIE, III, IIIF, IIIG, IIH
GM T IV
GM Type A
GM 88900925, GM 9986195 (Aisin AW, JWS 3309)
Honda/Acura ATF Z1, DW-1, Premium
Honda Z-1
Hyundai NWS-9638, SP-II, SP-III, Apollo Red 1K
JWS 3314, JWS 3317
Idemitsu K17, Jatco 3100, PL085, ATF Red 1
Isuzu Besco ATFII, ATF III, Genuine ATF
Jaguar ATF 3403 M115, LT 71141, JLM 20238, 8342
JASO 1-A
JASO 2A-02

JATCO FWD in Nissan, Rover 800, VW Polo (Texaco N402)
JATCO – Jaguar X Type 2001-2005 (Idemitsu K-17)
JATCO 3100 PL085
JEEP ATF+3, ATF+4
JWS 3309 (Aisin Warner)
JWS 3309 (T-IV)
Kia ATF Red 1, SP-II, SP-III, Apollo Red 1K
Landrover LT 71141, TYK500050
MAN 339F, V1, V2, Z1, Z2, Z3
Maserati 231603
Mazda ATF- M III
Mazda ATF- MV
Mercedes Benz 223.1, 236.1, 236.2, 236.3, 236.5, 236.6, 236.7, 236.9, 236.10, 236.11, 236.15, 236.41, 236.81
MB ZF 4 HP20
MB 5 Speed 1996-2006 (Shell 3403)
MB 722.3, 722.4, 722.5, 722.6, 722.9
Mini Cooper 83-22-0 402 413 9 (JWS 3309, T IV)
Mitsubishi Diamond SP-II, SP-III, J2, Dia, ATF PA
Mitsubishi Diaqueen ATF J3
Nissan/Infinity Matic D/J/K/S/W 402
NAG 1 (Jeep Cherokee), NAG 2 (Chrysler)
Opel (All vehicles)
Peugeot ZF 4 HP20, AL-4 (PSA)
Porsche ATF 3403-M115, LT 71141, T IV (JWS 3309)
Queen J2, J3
Renault DP-0
Renk Doromat
Saab T IV (JWS 3309) 93 165 146
Saab 93 160 393, Aporoil
Saturn T IV (JWS 3309), 22689186
Scion (all vehicles)
PL085,ATF Red 1
Isuzu Besco ATF II, ATF III,Genuine ATF
Shell M 115, L12108
Shell 3403, 3353, LA2634, M-1375.4, .5, .6, M-12108, ATF-134
SP-II SP-III
Subaru ATF, ATF HP, KO140Y0700, SOA868V9241
Suzuki ATF 3309, 3314, 3317
Texaco ETL-7045E
Texaco ETL-8072B, N402
Toyota T, T-II, T-III, T-IV, D-2
Voith G607 G13636 (55.6336.XX)
Voith Turbo H55.6335.3X
Volvo 97340, 97341, T IV (JWS 3309) Pass. Car
Volvo 1161521, 1161540, 1161640, 1161621, 31256774, 31256675
VW 5 HP LT 71141 (ZF 5 HP 18FL, 19FL, 24A)
VW 5 HP LT 71141 (VW G-052-162-A1, A2)
VW G-052-182-A2
VW 5 HP (ZF 5 HP 30)
VW TL 521 62
VW TL 52162, 52533
ZF 3 and 4 speed transmissions
ZF TE ML 02F, 03D, 04D, 05L, 09, 11A, 11B, 14A, 14B, 14C, 16L, 16M, 17C, 20B, 20C, 21L
ZF Lifeguard Fluid 6



Australian Made & Owned Oil Company



Proven Protection. Powerful Performance.